

~~TOP SECRET~~

DISPATCH NO. [REDACTED] - 0277

13 November 1956

25X1A

TO :

25X1A

FROM : Chief of Station, [REDACTED]

SUBJECT : GENERAL - OPERATIONS

25X1A

Specific: [REDACTED] (Commander's Report)

25X1A

1. This is Commander's Report on Mission No. 1323, [REDACTED] flown on 12 November 1956, [REDACTED] No. 352.

25X1A
25X1A

25X1A

2. [REDACTED] Performance: Excellent.

3. Weather: Slightly more cloud than forecast. More haze than forecast. Haze and low sun angle restricted visibility near end of mission.

25X1A

4. [REDACTED] R6 shutter failure - broken cam - time not known. [REDACTED] failure - scan motor burned out after 225 feet.

25X1A

25X1A

5. [REDACTED] "S" - all equipment functioned properly.

25X1A

6. [REDACTED] Performance: Excellent.

[REDACTED] 25X1A

25X1A

ORIGINATOR: [REDACTED]

DOCUMENT NO. _____
NO CHANGE IN CLASS. ☐
☐ DECLASSIFIED
CLASS. CHANGED TO: TS 0 2012
NEXT REVIEW DATE: _____
AUTH: HR 70-2
DATE: 10 MAR 1992 REVIEWED: 064540

T/S #160102

Copy 2 of 2
Page 1 of 1

~~TOP SECRET~~